



GLOVE CARE GUIDE

PROPER CARE FOR BETTER PROTECTION

CUT-RESISTANT GLOVES- LEVEL C

(ถุงมือกันบาด ระดับ C)

Washing Instructions

- Hand wash or machine wash on a gentle cycle at a maximum temperature of 40°C.
- Use a mild, pH-neutral detergent.
- Do not use bleach, chlorine, fabric softener, or harsh detergents, as they may damage the HPPE and glass fibers.
- Do not soak for long periods, scrub with a brush, or wash with sharp or abrasive items.
- Rinse thoroughly to remove all detergent residue.
- Gently squeeze out excess water. Do not wring.
- Washing may affect cut resistance and grip performance. Inspect the gloves before each reuse.

Drying Instructions

- Air-dry naturally in a shaded, well-ventilated area.
- Reshape the gloves before drying.
- Do not tumble-dry, iron, use hot air, or place near heat sources or open flames.
- Make sure the gloves are completely dry before use or storage.

After washing, stop using and replace the gloves if you find cuts, tears, exposed glass fibers, loose seams, or deformation. If the manufacturer prohibits washing or provides specific care instructions, always follow the manufacturer's guidance.



Extend
Glove Life



Maintain
Performance



Ensure
Protection



Work
Safely