



GLOVE CARE GUIDE

PROPER CARE FOR BETTER PROTECTION

CUT-RESISTANT ARM SLEEVES – LEVEL 5D

(ปลอกแขนกันบาดระดับ 5D แบบเจาะนิ้วโป้ง)

Washing Instructions

- Hand wash or machine wash on a gentle cycle at a maximum temperature of 40°C.
- Use a mild, pH-neutral detergent.
- Wash separately from clothing, sharp objects, lint-producing materials, and abrasive items.
- Do not use bleach, chlorine, fabric softener, solvents, or harsh detergents, as they may damage the HPPE, glass fibers, and nylon.
- Do not soak for long periods, rub vigorously, or scrub with a stiff brush, as this may deform the seamless knitted structure and thumbhole.
- Rinse thoroughly to remove all detergent residue.
- Gently squeeze out excess water. Do not wring.
- Wash only when necessary, as repeated washing may reduce fit and cut-resistant performance.

Drying Instructions

- Reshape and lay flat to air-dry in a shaded, well-ventilated area.
- Reshape the thumbhole and do not hang the sleeve in a way that may cause stretching.
- Do not tumble-dry, iron, use hot air, or expose the sleeve to direct heat.
- Keep away from direct sunlight, open flames, and high temperatures.
- Dry completely before use or storage.
- Store in a clean, dry place away from moisture, oil, chemicals, and sunlight.



Extend
Glove Life



Maintain
Performance



Ensure
Protection



Work
Safely