



# GLOVE CARE GUIDE

PROPER CARE FOR BETTER PROTECTION

## BLACK PU COATED GLOVES

(ถุงมือโพลีเอสเตอร์เคลือบ PU สีดำ)

### Washing Instructions

- Hand wash or machine wash at a water temperature not exceeding 40°C.
- Use a mild detergent. Avoid bleach, chlorine, and fabric softener.
- Do not soak the gloves for prolonged periods or scrub them vigorously, as this may damage the PU coating.
- Wash separately from colored fabrics, sharp objects, and abrasive materials.
- Rinse thoroughly and gently squeeze out excess water. Do not wring.

### Drying Instructions

- Allow the gloves to air-dry naturally in a well-ventilated area.
- Reshape the gloves before drying.
- Keep away from direct sunlight, direct heat, and open flames.
- Do not tumble-dry or iron, as heat may cause the PU coating to crack, peel, or deform.
- Ensure that the gloves are completely dry before storage to prevent musty odors and mold growth.
- Inspect the gloves after every wash. Replace them immediately if the coating is peeling, the gloves are torn, or their grip performance has deteriorated.

### Inspect the gloves after every wash.

Replace them immediately if the coating is peeling, the gloves are torn, or their grip performance has deteriorated.



Extend  
Glove Life



Maintain  
Performance



Ensure  
Protection



Work  
Safely