



GLOVE CARE GUIDE

PROPER CARE FOR BETTER PROTECTION

POLYMAX 10G POLYESTER GLOVES

(ถุงมือถักโพลีเอสเตอร์ POLYMAX 10G)

Washing Instructions

- Hand wash or machine wash on a gentle cycle at a maximum temperature of 40°C.
- Use a mild, pH-neutral detergent.
- Wash separately from colored fabrics, lint-producing materials, sharp objects, and abrasive items.
- Do not use bleach, chlorine, fabric softener, solvents, or harsh detergents.
- Do not soak for long periods or scrub with a stiff brush, as this may damage the fibers and deform the 10-gauge knitted structure.
- Rinse thoroughly to remove all detergent residue.
- Gently squeeze out excess water. Do not wring.

Drying Instructions

- Reshape and air-dry in a shaded, well-ventilated area.
- Lay flat or hang carefully to prevent stretching.
- Do not tumble-dry at high temperatures, iron, or use hot air.
- Keep away from direct sunlight, open flames, and direct heat.
- Dry completely before use or storage.
- Store in a clean, dry place away from oil, chemicals, and sunlight.

Inspect the gloves after washing and before every use. Replace them if you find holes, tears, loose seams, frayed fibers, stretching, or deformation.

Note: Uncoated polyester gloves are suitable for general handling. They should not be described as cut-resistant unless tested and rated under a relevant standard, such as EN 388.



Extend
Glove Life



Maintain
Performance



Ensure
Protection



Work
Safely