



GLOVE CARE GUIDE

PROPER CARE FOR BETTER PROTECTION

POLYMAX 13G POLYESTER GLOVES

(ถุงมือถักโพลีเอสเตอร์ POLYMAX 13G)

Washing Instructions

- Hand wash or machine wash on a gentle cycle at a maximum temperature of 40°C.
- Use a mild, pH-neutral detergent.
- Wash separately from colored fabrics, lint-producing materials, sharp objects, and abrasive items.
- Do not use bleach, chlorine, fabric softener, solvents, or harsh detergents.
- Do not soak for long periods or scrub with a stiff brush, as this may damage the fibers or deform the knitted structure.
- Rinse thoroughly to remove all detergent residue.
- Gently squeeze out excess water. Do not wring.

Drying Instructions

- Reshape and air-dry in a shaded, well-ventilated area.
- Lay flat or hang carefully to prevent stretching.
- Do not tumble-dry at high temperatures, iron, or use hot air.
- Keep away from direct sunlight, open flames, and direct heat.
- Dry completely before use or storage.
- Store in a clean, dry place away from oil, chemicals, and sunlight.

Inspect the gloves after washing and before every use. Replace them if you find holes, tears, loose seams, frayed fibers, stretching, or deformation. Always follow the care instructions on the label or those provided by the manufacturer.

Product information note: The product name states 13G, while the description states 10 gauge. Verify and correct this information for consistency. If this is the POLYMAX 13G model, use the description “fine 13-gauge knitted structure.” Do not describe the gloves as cut-resistant unless they have been tested and rated under a relevant standard, such as EN 388.



Extend
Glove Life



Maintain
Performance



Ensure
Protection



Work
Safely